

CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
ErgWind Srl	83 sites in 2013 and 14 sites in 2014	Construction H&S Service (Health & Safety Coordination service both in design and execution phases)			2013 - ongoing
Wind International Italy (BKW)		H&S Site Inspection, H&S Audit			2012 - ongoing
Availon Srl – Avaiolon Gmbh		Occupational H&S Services (Risk assessment) and H&S Site Inspection/H&S Audit			2011 - ongoing
Group MACHIELS	3 Wind Farms in Belgium	Health & Safety Coordination		Belgium	2013 to 2014
Repower Italy SrI (part of Repower group)		HSE Laws and Regulations Assessment		Romania and Croatia	2013
Repower Italy SrI (part of Repower group)	Bestepe Wind Farm	Construction H&S Support Service		Romania	2013
Vestas	Talara and Cupisnique Wind Farm	Health & Safety Coordination	62 Wind Turbines 1,8 MW Vestas V100	Peru	2013





CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
MARTIFER Solar	Wind Farm in Ukraine	Health & Safety Coordination		Ukraine	2012
Northwind Offshore Energy	Wind Farms in Belgium	Health & Safety Coordination	Offshore Wind Farm	Belgium	2011 to 2012
Solaria		Direction of Works and Health & Safety Coordination			2011 to 2012
Enersis Group	Several Wind Farms in Portugal	Health & Safety Coordination		Portugal	2004 to 2012
Acciona	Oaxaca Wind Farm	Construction Supervision	Onshore Wind Farm	Mexico	2011
Alstom	Supply Chain Project	NDT, Material Testing, Inspection	Bearing & Housing, Hub, Gearbox	China	2011
Cliford Chance Sp. z o.o.	Marszewo Wind Farm	Tender, Technical Support	Onshore Wind Farm 41 WTGs	Poland	2011
DZP Sp. z o.o.	Wicko Wind Farm	Tender, Technical Support	Onshore Wind Farm 20 WTGs	Poland	2011
Huarun	2 Wind Farms	End-of-Warranty Inspections	Wind Turbine: 41 Goldwind 750 Kw and 9 Vestas V90 2 MW	China	2011





CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
Iberdrola Renovables	Vieiro Wind Farm	Gearbox Endoscopy	Gearbox; Wind Turbine Gamesa G52	Spain	2011
Iberdrola Renovables	Wind Turbine	Thermographic Inspection	Groundbox; Transformer and medium Voltage Box. 142 Gamesa G52 and 108 Gamesa G58 in 8 Wind Farms	Spain	2011
Martifer Renewables	Rymanów Wind Farm	Tender Support	Onshore Wind Farm 13 WTGs	Poland	2011
RWE Renewables Polska Sp. z o.o.	Nowy Staw Wind Farm	Owner's Representative, Tender Support, Construction Supervision, QA/QC Management and Inspection, Manufacturing Supervision, Final Acceptance Inspection	Onshore Wind Farm 19 WTGs	Poland	2011
Termall Sp. z o.o.	Gluchów Wind Farm	Tender Support	Onshore Wind Farm 10 WTGs	Poland	2011
Park Wiatrowy Tychowo (Owner RWE Renewables Polska Sp. z o.o.)	Tychowo Wind Farm	Owner's Representative, Tender Support, Construction Supervision, QA/QC Management and Inspection, Manufacturing Supervision, Final Acceptance Inspection	Onshore Wind Farm 15 WTGs x 2,3 MW	Poland	2010 to 2011





CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
Vestas	Cadiz, Almeria, Lugo, Orense and Valladolid Wind Farms	Health & Safety Coordination	Onshore Wind Farm	Spain	2006 to 2011
CGN WIND POWER CO., LTD	Supply Chain Project	Supplier Assessment	Hub, Flange, Tower	China	2010
Eko Energy Sp. z o.o.	Kobylnica Wind Farm	Owner's Representative, Tender Support, Construction Supervision, QA/QC Management and Inspection, Manufacturing Supervision, Final Acceptance Inspection	Onshore Wind Farm 18 WTGs x 2,3 MW	Poland	2010
Enel green power		Due diligence			2010
Gamesa	Inner Mongolia Wind Farm/Putian Nanri Wind Farm	Supply Chain Services, Installation Quality Inspection, NDT	Wind Turbine	China	2010
Green Power Polska Sp. z o.o.	Pomorze WF	Owner's Representative, Tender Support, Construction Supervision, QA/QC Management and Inspection, Manufacturing Supervision, Final Acceptance Inspection	Civil & Electrical Works, 110 kV Substation, Components and Complete Wind Turbines	Poland	2010





CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
Guodian UPC	24 Wind Farms	Manufacturing Supervision, QA/QC Management and Inspection	Tower	China	2010
PEP – Polish Energy Partners S.A.	Łukaszów Wind Farm	Owner's Representative, Tender Support, Construction Supervision, QA/QC Management and Inspection, Manufacturing Supervision, Final Acceptance Inspection	Onshore Wind Farm 17 WTGs x 2,0 MW	Poland	2010
PEP – Polish Energy Partners S.A.	Modlikowice Wind Farm	Owner's Representative, Tender Support, Construction Supervision, QA/QC Management and Inspection, Manufacturing Supervision, Final Acceptance Inspection	Onshore Wind Farm 12 WTGs x 2,0 MW	Poland	2010
FLUOR LIMITED	Greater Gabbard Offshore Wind Project, UK	NDT, Manufacturing Supervision, QA/QC Management and Inspection	CAN (Mono-Piles & Transition Pieces)	China	2008 to 2010





CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
Park Wiatrowy Suwałki (Owner RWE Renewables Polska Sp. z o.o.)	Suwałki Wind Farm	Owner's Representative, Tender Support, Construction Supervision, QA/QC Management and Inspection, Manufacturing Supervision, Final Acceptance Inspection	Onshore Wind Farm 18 WTGs x 2,3 MW	Poland	2008 to 2010
Airtricity	Butendiek	Project Certification	Offshore Wind Farm	Germany	2009
Belwind Offshore Energy	Bligh Bank Offshore Wind Farm, Belgium	Technical Consultancy, QA/QC Management and Inspection	Vestas V90 Wind Turbines	Belgium	2009
Centrica Energy	Lincs Offshore Wind Farm Project	Risk Management Consultancy	Project Consultancy	UK	2009
China Light & Power	82 MW Saundati Wind Farm	Inspection	Civil foundations, mechanical and electrical installations	India	2009
China Light & Power	99 MW Theni Wind Farm	Inspection	Civil foundations, mechanical and electrical installations	India	2009
EDF Energy Renewables	Cemmaes Wind Farm	Failure Analysis	Project Consultancy	UK	2009
Enel		Technical Due Diligence	Onshore Wind Farm	Italy	2009
Enel-Union Fenosa		Blade Inspection, Ultrasonic Testing		Spain	2009





CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
Engy AB	Klafsön Wind Farm, Sweden	Failure Analysis	Vestas V25 Wind Turbine	Sweden	2009
ENOVA	Delta Nordsee (Delta II) Offshore Wind Farm, Germany	Project Certification	Offshore Wind Farm	Germany	2009
FRI-EL (RWE)	Wind Farm San Basilio/Sardinia	QA/QC Management and Inspection, Visual Inspection and Quality Document Review		Italy	2009
LCO Nature c/o Evelop Germany GmbH	OWP WEST	Project Certification	Offshore Wind Farm	Germany	2009
NN	Onshore Wind Farm Project	Blade Inspection and NDT, Failure Analysis	Wind Turbine 850 KW	Spain	2009
Nordsee Wind- power GmbH	Global Tech I	Project Certification	Offshore Wind Farm	Germany	2009
Northern Energy	Gaia II, Gaia III, Gaia IV, Global Tech II, Global Tech III, Sea Storm I, Sea Storm II, Sea Wind III, Sea Wind IV	Project Certification	Offshore Wind Farm	Germany	2009





CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
Park Wiatrowy Tychowo Sp. z o.o	Tychowo Wind Farm	Tender Support	Onshore Wind Farm	Poland	2009
PEP – Polish Energy Partners S.A.	Łukaszów Wind Farm	Tender Support	Civil & Electrical Works, 110 kV Substation, Components & Complete Wind Turbines	Poland	2009
PEP – Polish Energy Partners S.A.	Modlikowice Wind Farm	Tender Support	Civil & Electrical Works, 110 kV Substation, Components & Complete Wind Turbines	Poland	2009
PNE WIND AG	Gode Wind III	Project Certification	Offshore Wind Farm	Germany	2009
RWE		QHSE Consultancy	Offshore Wind Farm	UK, Germany	2009
RWE Npower Renewables	Rhyl Flat Offshore Wind Farm Project	HSE Audits, HSE Management and Supervision	Project Consultancy	UK	2009
Senter Novem	Egmond aan Zee Offshore Wind Farm, the Netherlands	Manufacturing Inspection	Offshore Wind Farm	The Nether- lands	2009

 ${\sf SGS}$  is the world's leading inspection, verification, testing and certification company.





CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
Repower	Blade Inspection	Blade Inspection at the factory (resident inspection)	Blades	China	2008 to 2009
Vestas/Repower	NDT Project	NDT Services	Bearing & Housing, Hub, Frame, Edge Frame	China	2006 to 2009
China Light & Power	100 MW Samana Wind Farm	Inspection	Civil foundations, mechanical and electrical installations	India	2008
Edison Mission Energy		Vendor Assessment/Technical Audit	Gearboxes	Germany	2008
Edison Mission Energy		Vendor Assessment/Technical Audit	Towers and Nacelle	India	2008
Edison Mission Energy	Buffalo Bear and Elkhorn Ridge Wind Farms, USA	Construction Supervision, Final acceptance Inspections, Commissioning Survey	9 Suzlon S88 Wind Turbines and 27 Vestas V90 Wind Turbines	USA	2008
EnBW Energie Baden-Würt- temberg AG	4 Offshore Wind Farms, Germany	Technical Due Diligence	Offshore Wind Farms	Germany	2008
John Deere Wind Energy	Sunray and Brewster Wind Farms, USA	End of Warranty Inspections, QHSE Consultancy, In-Service Inspections	Suzlon S64 Wind Turbines	USA	2008
John Deere Wind Energy	Pipestone, Minnesota	Technical Consultancy	Suzlon S64 and S88 Wind Turbines	USA	2008





CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
LCO Nature c/o Evelop Germany GmbH	Albatros Offshore Wind Farm, Germany	Project Certification	Offshore Wind Farm	Germany	2008
Longyuan	7 Wind Farms	Manufacturing Supervision, QA/QC Management and Inspection	Tower: GE and Jinfeng	China	2008
Park Wiatrowy Suwałki Sp. z o.o. (company related to RWE Innogy GmbH)	Suwałki Wind Farm	Owner's Representative, Tender Support, Construction Supervision, QA/QC Management and Inspection, Manufacturing Supervision, Final Acceptance Inspection	Civil & Electrical Works, 110 kV Substation, Components and Complete Wind Turbines	Poland	2008
PEP – Polish Energy Partners S.A.	Łukaszów Wind Farm	Technical Due Diligence	Onshore Wind Farm	Poland	2008
PEP – Polish Energy Partners S.A.	Modlikowice Wind Farm	Technical Due Diligence		Poland	2008
PNE WIND AG	Gode Wind II	Design Verification & Site Assessment of Wind Turbine and Foundation	Offshore Wind Turbines	Germany	2008





CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
PROKON Nord Energie- systeme GmbH	Cote d'Albatre, MEG I	Project Certification, Manufacturing Supervision	Offshore Wind Farm	Germany, France	2008
Trianel	Borkum West II	Project Certification	Offshore Wind Farms	Germany	2008
WE Energies	Blue Sky Green Field	Final Acceptance Inspection, Commissioning Survey	80 Onshore Wind Turbines	USA	2008
Grupo GENERG	Several Wind Farms in Portugal	Health and Safety Coordination		Portugal	2005 to 2008
Acciona Wind Power	Tatanka Wind Farm Project, South Dakota, USA	QHSE Consultancy, HSE Audits	120 x 1.5 MW Wind Turbine Onshore Wind Farm	USA	2007
Green Power Polska Sp. z o.o.	Ustka Wind Farm	Owner's Representative, Tender Support, Construction Supervision, QA/QC Management and Inspection, Manufacturing Supervision, Final Acceptance Inspection	Onshore Wind Farm 240 MW	Poland	2007
Skypower Coorporation	Fuhrländer	Technical Due Diligence	Onshore Wind Turbines	Germany	2007





CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
Vedanta Group	38.4 MW Samana Wind Farm	Construction Supervision	Civil Foundations, Mechanical and Electrical Installations	India	2007
Nordex	Ningxia Helanshan Wind Farm, Changdao Wind Farm	Manufacturing Supervision, QA/QC Management and Inspection, Installation Inspection	Tower/Main Frame	China	2006 to 2007
Elsam	Burbo Offshore Wind Farm, UK	Coating Inspection	Monopiles	Belgium	2006
Sinovel	44 Wind Farms	Manufacturing Supervision, QA/QC Management and Inspection	Tower	China	2006
Vattenfall	Kriegers Flak - Offshore Wind Farm, Sweden	Design Assessment Inspections, NDT of Materials, Manufacturing Supervision, Final Acceptance Inspection, Construction Supervision, Commissioning Survey, Project Certification	Cables, Foundations, Towers, Blades, Gearboxes, Wind Turbine, Transformer, Offshore Substation	Germany	2006
PEP – Polish Energy Partners S.A.	Puck Wind Farm	Owner's Representative, Vendor Assessment/Technical Audit, Construction Supervision, Final Acceptance Inspection, Manufacturing Supervision	Onshore Wind Farm 10 WTGs x 2,0 MW	Poland	2005 to 2006





CLIENT	PROJECT	SCOPE OF SERVICE	FOCUS	EXECUTION COUNTRY	YEAR
PEP – Polish Energy Partners S.A.	Puck Wind Farm	Owner's Representative, Vendor Assessment/Technical Audit, Construction Supervision, Final Acceptance Inspection, Manufacturing Supervision	Infrastructure, Components and Complete Wind Turbines	Poland	2005
PEP – Polish Energy Partners S.A.	Suwałki and Tychowo Wind Farm	Owner's Representative, Vendor Assessment/Technical Audit Construction Supervision, Final Acceptance Inspection, Manufacturing Supervision	Infrastructure, Components and Complete Wind Turbines	Poland	2005
Tai-Power	Changkong Onshore Wind Farm, Taiwan	Manufacturing Supervision, Construction Supervision, Final Acceptance Inspection, NDT, Inspections, Vendor Assessment/Technical Audit	2 MW Vestas V80 Wind Turbines, Towers	Denmark, Taiwan, Vietnam	2005
Elsam	Horns Rev Offshore Wind Farm, Denmark	Failure Analysis of Coating Problems, Technical Consultancy	Monopiles, Transition Pieces, Towers, Boat Landings, Platform	Belgium	2004
Grupo Enersis	Several Onshore Wind Farms, Portugal	Construction Supervision	Cables, Foundations, Towers, Nacelles, Hubs, Blades	Portugal	2004
Enel		QA/QC Management and Inspection	Blades, Cables, Generators, Towers	Spain, Italy, Brazil	2003

